

# **TOWN OF NEW WINDSOR FIRE INSPECTOR'S OFFICE**

## **MEMO**

**TO:** MARK J. EDSALL, P.E. -- P.B. ENGINEER

**FROM:** ROBERT F. RODGERS,  
FIRE INSPECTOR

**DATE:** 7 NOVEMBER 2002

**SUBJECT:** GMH MILITARY HOUSING PROJECT 02-16, 02-17 & 02-18

Dear Mark:

The following are my comments of above referenced projects:

Hydrants are not placed every 500' along the water main as per Local Law and also, need hydrants at intersections.

RFR:mlm